
## County Durham and Darlington Fire and Rescue Service



#### **Protecting Heritage Buildings and artefacts from Fire**

Example Floor Hazard Plan and artefact grab sheets






	KEY
A	Electrical control
77	panel
Ā	Sink/water outlet
⊗ <b>W</b>	Stop cock
	Main electrical
	switch
$\otimes \mathbf{G}$	G as isolation
o.σ	valve
IP	Fire Alarm
ur.	Indicator Panel
	Boiler
X	Toolbox
E	Exit
H	Hydrant

Ist G Basement Stanchions and ropes are used throughout the property to guide visitors and these may be a hazard in a recovery situation.
Also, shutters may be in place over windows. These are not locked but latched. Sash windows may be used for access/egress for object removal. These may be locked or painted shut.


Chemical cupboard high level - white spirit; silver dip; kerosene/vinegar mix; wax polish; bleach. Not locked. Not kept in metal cabinet






	KEY						
4	Electrical control panel						
<u>.</u>	Sink/water outlet						
$\otimes$ W	Stop cock						
	Main electrical switch						
$\otimes \mathbb{G}$	Gas isolation valve						
IP	Fire Alarm Indicator Panel						
1	Boiler						
X	Toolbox						
B	Exit						
H	Hydrant						

## Ground Floor Gallery





## First Floor Gallery

## **Priority 1**

Painting: Night Sky 'The Stars at Night' by T. Jones Inventory no: 3.1950

160cm







#### Removal: Unhook Chain

Wet or Damp	Contaminated	Broken	Weak	Dangerous to Handle	Mouldy	Smoke Damaged	Other

Pack As Is	Dry	Keep Wet	Wash then	Other
	and Pack	and Freeze	Dry	

# **Ground Floor Drawing Room**





# First Floor Drawing Room Priority 2 Carved Mahogany Library Chair Inventory no: 88.1930

80cm ——



100cm




#### Removal:


Carry chair by base.

	Object inclinational								
Wet or	Contaminated	Broken	Weak	Dangerous	Mouldy	Smoke	Other		
Damp				to Handle		Damaged			

Pack As Is	Dry and Pack	Keep Wet and Freeze	Wash then Dry	Other
			_	

### First Floor Red Bedroom






#### First Floor Red Bedroom

## **Priority 1**

# Japanese Ceramic Vase Inventory no: 45.1950






#### Removal:


- Hold carefully from base.

Wet or Damp	Contaminated	Broken	Weak	Dangerous to Handle	Mouldy	Smoke Damaged	Other

Pack As Is	Dry and Pack	Keep Wet and Freeze	Wash then Dry	Other

## **Ground Floor Office**





## **Ground Floor Office**

# Priority 2 Architectural Investigation Project Files





#### Removal:

- Remove all files from the cabinet (not locked)
- Place files into a crate and store securely

Wet or Damp	Contaminated	Broken	Weak	Dangerous to Handle	Mouldy	Smoke Damaged	Other

Pack As Is	Dry and Pack	Keep Wet and Freeze	Wash then Dry	Other

